DANGER

CRUSHING/ SHEARING HAZARD

DO NOT ENTER!

Keep all body parts out of machine during operation.

Failure to comply will result in serious injury or death.